



## FY-30A Firmware For Multimotor


1. Put the USB-TTL connecting wire to your computer, then open the upgrade software and choose the port.




2. after inserting the USB-TTL connecting wire to the UART in FY-30A, you will see " connect success ".if you failed to connect it, pls check the first and second steps again.




3. Click "Select Firmware" choose the firmware .




4. click " start upgrade ", then pls keep waiting for the upgrade.




5. after upgrading, please pull out the USB-TTL connecting wire in FY-30A, then connect it to FY-30A again. Restart the FY-30A again and check whether it has upgraded to a new version.





Connect again

6. click " read the version number ", if you see " fy-30, Version Number:2.00 ", it means you upgrade successful at last.



7. regulate the knob to default position of multimotor firmware, it's about at the middle.  
After that you can install that in the multimotor aircraft, more installment instructions can be found in the FY-30A multimotor firmware instal manual.

